1st & final bill

**M. A. R. 57 (Rule 116)**
Measurement Book

No. D 63101

Serial No. .....

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

| Date | Full description, etc, of work | Dimensions | | | | Contents | Reference to last Measurement |
|---|---|---|---|---|---|---|---|
| | | Number | Length | Breadth | Depth | | |
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 |
| | Name of work :- providing and Improvements Drinking water facilities in ward no 13. Mallasandra. | | | | | | |
| | W.O :- BBMP/EE/DD/WO/127/2017-18. dated :- 18-12-17. | | | | | | |
| | Job code :- 013-18-000061 | | | | | | |
| | A.A :- EE/DD/AS/547/17-18. dated :- 27-11-17. | | | | | | |
| | TS :- CE/TS/272/17-18 dated :- 27-11-17. | | | | | | |
| | Agr :- EE/DD/AGR/127/2017-18. dated 18-12-2017. | | | | | | |
| | Est cost :- RS. 100.00 Lakhs. | | | | | | |

Scanned by CamScanner

**M. A. R. 57 (Rule 116)** **No. D**

Measurement Book

63105

Serial No. .....

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

| Date | Full description, etc, of work | Number | Dimensions Length | Breadth | Depth | Contents | Reference to last Measurement |
|---|---|---|---|---|---|---|---|
| 1 | 2 | 3 | 4 | | 5 | 6 | 7 | 8 |
| | Roof Slab | | | | | | |
| | Slab | 1 X | 5.70 x | 3.75 x | 0.15 | 3.206 | |
| | | 1 X | 5.70 x | 3.75 x | 0.15 | 3.206 | |
| | | | | | | 12.15 $m^3$ | 10/01/18 |
| | | @ Rs | 6876.36 /$m^3$ | | | — | Rs. 83564=00 |
| 9. | Providing and laying in plain cement concrete of mix 1:2:4 with cement @ 240 kgs, @ with 20mm and down size graded granite metal coarse aggregates @ 0.878 cum. It is completed as per Specification. | | | | | | |

Scanned by CamScanner

# MEASUREMENT BOOK

| Date | Full description, etc, of work | Dimensions | | | | Contents | Reference to last Measurement |
|---|---|---|---|---|---|---|---|
| | | Number | Length | Breadth | Depth | | |
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 |
| 9. | Supplying and drawing 3 core PVC sheathed submersible pump cable manufactured with electrolytic grade copper with flexible copper conductor. It is completed as per specification. | | | | | 2032.00 M | |
| | | | @ Rs. | 164.29/m | | — | Rs. 333827.00 |
| 10. | Supplying & delivery at site brand new / Essen / Lotus Sunsines / Adarsh / GK controls best indigenous make combine energy meter-cum-control panel. It is completed as per Specifn | | | | | | |
| | | 1 | — | — | — | 1 | |
| | | | | | — | 1 | |

Scanned by CamScanner

# MEASUREMENT BOOK

| Date | Full description, etc. of work | Dimensions | | | | Contents | Reference to last Measurement |
|---|---|---|---|---|---|---|---|
| | | Number | Length | Breadth | Depth | | |
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 |
| | | 1 | – | – | – | 1 | |
| | | 1 | – | – | – | 1 | |
| | | 1 | – | – | – | 1 | |
| | | 1 | – | – | – | 1 | |
| | | | | | | 4 No's | |
| | ನಕಾಯಕ ಕಾಯಿಯವರಿಗೆ ಕುಳಿತುಕೊಳ್ಳಲು ಕೆಬ್ಬಿಹಳ್ಳಿ ಬಸವಣ್ಣ ದೇವಸ್ಥಾನ, ದಾಸರಹಳ್ಳಿ ವಲಯ ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ ಎಸ್.ಎಂ. ರಸ್ತೆ, ರಬೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು | | @ Rs. | 900.00 | | — | Rs. 3600=00 |
| 39. | providing and fixing benches | | | | | | |
| | | 50 | – | – | – | 50 No's | |
| | | | @ Rs | 9200/= | | | Rs. 460000=00 |

Scanned by CamScanner

**M. A. R. 57 (Rule 116)** **No. D**

Measurement Book

63158

Serial No. .....

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

| Date | Full description, etc, of work | Dimensions | | | | Contents | Reference to last Measurement |
|---|---|---|---|---|---|---|---|
| | | Number | Length | Breadth | Depth | | |
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 |
| | | | | | Total | - | Rs. 89,38,594=00 |
| | | | KRIDL | | Charges (10+1)% | - (+) | Rs. 9,83,245=00 |
| | | | | | Grand Total | - | Rs. 99,21,839=00 |
| | Certificate<br>Certified that the work is executed saticifactorily done.<br>15/1/18 | | | | | | |

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಕೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

Scanned by CamScanner

# MEASUREMENT BOOK

| Date | Full description, etc. of work | Dimensions | | | | Contents | Reference to last Measurement |
|---|---|---|---|---|---|---|---|
| | | Number | Length | Breadth | Depth | | |
| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 |
| | ① cambridge school<br>Basaveshwara Road<br>② 2nd cls muneshwara block<br>Vishal School Road<br>25th cls BHEL Main colony<br>Ravindra nagr<br>2nd cls Santhosh nagr<br>④ | | | | | | |
| | | | | | Index :-<br>Bore well - ⊕ | | Locations :-<br>① cambridge School Road<br>② 2nd cls muneshwara blk<br>③ 25th cls BHEL main colony<br>④ 2nd cls Santhosh nagr. |

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬೆಟ್ಟಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬಿಬಿಎಂಪಿ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ರಾಜರಾಜೇಶ್ವರಿನಗರ, ಬೆಂಗಳೂರು

Scanned by CamScanner

**M. A. R. 57 (Rule 116)** **No. D**

Measurement Book

63159

Serial No. .....

Name of work ..... From ..... To .....

Name of Contractor of nature of Agency.....

Date of commencement of work.....

| Date | Full description, etc, of work | Dimensions | | | Contents | Reference to last Measurement |
|---|---|---|---|---|---|---|
| | | Number | Length | Breadth / Depth | | |
| 1 | 2 | 3 | 4 | 5 / 6 | 7 | 8 |




Scanned by CamScanner